

ΣΕΙΡΑ ΙΝΩΝ RINGLIGHT			
Ονομασία προϊόντος	Κωδικός UDI	Αναφορά	Παρτίδες που επηρεάζονται
RINGLIGHT FIBER PROBE IR 1,8mm	03760227850129	ORLF000003	L00107673, L00107674, L00107697, L00107701, L00107753, L00107768, L00107771, L00107809, L00107864, L00107865, L00107878, L00107889, L00107923, L00108001, L00108257, L00108259, L00108265, L00108267, L00108382, L00108593, L00108970, L00109038, L00109094, L00109095, L00109103, L00110387, L00110529, L00110595, L00110607, L00110619, L00110632 Πεδίο εφαρμογής της επέκτασης: L00107989, L00108912, L00109023, L00109089, L00109628, L00110396, L00110446, L00110451, L00110457, L00110458, L00110536, L00110552, L00110573, L00110630, L00110631, L00113901, L00114295, L00114078
RINGLIGHT FIBER PROBE IR_SB 1,8mm	03760227850327	ORLF000003_ SB	Πεδίο εφαρμογής της παράτασης: L00107412, L00109795, L00109865, L00109868, L00109991, L00110007, L00110021, L00110127, L00112218, L00112279, L00112280, L00112431, L00112629, L00112979

ΣΕΙΡΑ ΙΝΩΝ RINGLIGHT			
Ονομασία προϊόντος	Κωδικός UDI	Αναφορά	Παρτίδες που επηρεάζονται
RINGLIGHT SLIM FIBER PROBE IRH 1,0mm	03760227850266	ORLF000005	L00107223, L00107360, L00107422, L00107463, L00109344, L00109450, L00109472, L00111011 Πεδίο εφαρμογής της παράτασης: L00107176, L00107199, L00107295, L00107302, L00107341, L00107395, L00107420, L00107576, L00107640, L00109145, L00109247, L00109252, L00109287, L00109329, L00109367, L00109415, L00109417, L00109431, L00110865, L00110866, L00110867, L00110870, L00110896, L00110913,
			L00110942, L00110947, L00111014, L00111021, L00111022, L00112576, L00112632, L00113050, L00113109, L00113111, L00113141, L00113150, L00113151, L00113160, L00113245, L00113291, L00113292, L00113344, L00113790, L00113818, L00113931, L00113940, L00114019, L00114021, L00114072